

CHEMICAL PARAMETERS

<u>CHEMICAL</u>	<u>IDEAL RANGE</u>
pH.....	7.5
FREE CHLORINE.....	2-5 ppm
HRR.....	+ / - 725
ALKALINITY.....	80-120 ppm
CALCIUM HARDNESS.....	300-500 ppm

To Raise PH

Soda Ash
Sodium Carbonate

To Lower PH

Muratic Acid
Sodium Bisulfate

To Raise Alkalinity

Sodium Bicarbonate
(Baking Soda)

To Lower Alkalinity

Muratic Acid
Sodium Bisulfate

To Raise Calcium Hardness

Calcium Chloride